

L Number	Hits	Search Text	DB	Time stamp
1	16	conveyor and clamping and cutters and stack\$4 same pallet	USPAT; US-PGPUB	2003/11/26 11:03
2	9	brick and cutters and stack\$4 same pallet	USPAT; US-PGPUB	2003/11/26 11:12
3	93	cutters and stack\$4 same pallet	USPAT; US-PGPUB	2003/11/26 11:20
4	0	20020129748.URPN.	USPAT	2003/11/26 11:19
5	1	108/\$.ccls. and cutters and stack\$4 same pallet	USPAT; US-PGPUB	2003/11/26 11:20
7	23745	108/\$.ccls. brick and stack\$4 same pallet	USPAT; US-PGPUB	2003/11/26 11:20
8	4	108/\$.ccls. and brick and stack\$4 same pallet	USPAT; US-PGPUB	2003/11/26 11:21
9	83	108/\$.ccls. and conveyor and stack\$4 same pallet	USPAT; US-PGPUB	2003/11/26 11:40
10	0	20020129748.URPN.	USPAT	2003/11/26 11:22
6	655	108/\$.ccls. and stack\$4 same pallet	USPAT; US-PGPUB	2003/11/26 12:33
11	0	6471461.URPN.	USPAT	2003/11/26 11:45
12	27	("0051727"   "0330100"   "0380366"   "0572391"   "0596975"   "0743344"   "0823580"   "0878252"   "0881492"   "0882605"   "1259227"   "2208208"   "2579783"   "3249073"   "3387882"   "3615088"   "3672312"   "3940181"   "4640326"   "5255724"   "5555819"   "5642803"   "5669314"   "5697753"   "5730068"   "RE36638"   "6062648").PN.	USPAT	2003/11/26 11:45
13	227	(block or brick) same stack\$4 same pallet	USPAT; US-PGPUB	2003/11/26 12:34
14	39	(block or brick) same conveyor same stack\$4 same pallet	USPAT; US-PGPUB	2003/11/26 12:34
15	9	4178122.URPN.	USPAT	2003/11/26 12:39
16	23	("2966018"   "2974812"   "3070240"   "3095678"   "3096891"   "3392851"   "3398675"   "3404788"   "3428192"   "3480161"   "3487954"   "3729084"   "3731785"   "3738514"   "3788495"   "3834298"   "3892318"   "3904043"   "3917081"   "3919372"   "3942651"   "3958506"   "4013183").PN.	USPAT	2003/11/26 12:40
-	639	brick and cut\$4 and recycl\$4	USPAT; US-PGPUB	2003/11/25 13:39
-	132	brick and cut\$4 and recycl\$4 and mortar and remov\$4	USPAT; US-PGPUB	2003/06/13 12:36
-	144	brick and cut\$4 and recycl\$4 and mortar	USPAT; US-PGPUB	2003/06/20 19:37
-	263	83/76.8	USPAT; US-PGPUB	2003/06/13 14:50
-	11	5249491.URPN.	USPAT	2003/06/13 13:51
-	7	("3983403"   "4188544"   "4196648"   "4468992"   "4541722"   "4640160"   "4941100").PN.	USPAT	2003/06/13 13:53
-	5558	225/\$.ccls.	USPAT; US-PGPUB	2003/06/13 14:27
-	825	125/13.01	USPAT; US-PGPUB	2003/06/19 15:33
-	2828	mortar and brick	USPAT; US-PGPUB	2003/06/19 15:34
-	573	125/23.01	USPAT; US-PGPUB	2003/06/19 15:34
-	98	125/26	USPAT; US-PGPUB	2003/06/19 15:54
-	7	125/26 and (mortar and brick)	USPAT; US-PGPUB	2003/06/19 17:17

-	1	5018504.URPN.	USPAT	2003/06/19 15:41
-	3	("1239480"   "3087483"   "4557246").PN.	USPAT	2003/06/19 15:42
-	4	4557246.URPN.	USPAT	2003/06/19 15:43
-	3	("0547746"   "1031107"   "1563081").PN.	USPAT	2003/06/19 15:44
-	4	4557246.URPN.	USPAT	2003/06/19 15:46
-	0	4004569.URPN.	USPAT	2003/06/19 15:47
-	2	3945151.URPN.	USPAT	2003/06/19 15:48
-	3	("1239480"   "3087483"   "4557246").PN.	USPAT	2003/06/19 15:48
-	1	3087483.URPN.	USPAT	2003/06/19 15:49
-	1	125/23.01 and (mortar and brick)	USPAT; US-PGPUB	2003/06/19 15:51
-	5	5662094.URPN.	USPAT	2003/06/19 15:51
-	2	125/13.01 and (mortar and brick)	USPAT; US-PGPUB	2003/06/19 15:52
-	26	3585980.URPN.	USPAT	2003/06/19 15:53
-	1	5018504.URPN.	USPAT	2003/06/19 15:55
-	0	4004569.URPN.	USPAT	2003/06/19 15:55
-	93	stacking and pallet and brick	USPAT; US-PGPUB	2003/06/20 19:13
-	19	stacking same pallet and chain same clamp	USPAT; US-PGPUB	2003/06/20 19:20
-	6	stacking same pallet and chain adj conveyor same clamp	USPAT; US-PGPUB	2003/06/20 19:21
-	51	125/13.01 and 125/23.01	USPAT; US-PGPUB	2003/06/20 19:35
-	100	chain adj conveyor same clamp	USPAT; US-PGPUB	2003/06/20 19:45
-	8	holding same clamp same (chain adj conveyor)	USPAT; US-PGPUB	2003/06/20 19:47
-	9	83/76.8.ccls. and cut\$4 and recycl\$4	USPAT; US-PGPUB	2003/11/18 18:27
-	10	125/13.01,26,23.01.ccls. and cut\$4 and recycl\$4	USPAT; US-PGPUB	2003/11/18 18:28
-	0	225/23.01.ccls. and cut\$4 and recycl\$4	USPAT; US-PGPUB	2003/11/18 18:28
-	0	225/ccls. and cut\$4 and recycl\$4	USPAT; US-PGPUB	2003/11/18 18:28
-	1	83/76.8.ccls. and brick and cut\$4 and recycl\$4	USPAT; US-PGPUB	2003/11/18 18:29
-	2	83/13.ccls. and brick and cut\$4 and recycl\$4	USPAT; US-PGPUB	2003/11/18 18:52
-	3	4085635.URPN.	USPAT	2003/11/18 18:29
-	5	("1316056"   "1670233"   "3059306"   "3492703"   "3838621").PN.	USPAT	2003/11/18 18:31
-	1	83/23,155,210168,425.3,435.ccls. and brick and cut\$4 and recycl\$4	USPAT; US-PGPUB	2003/11/18 18:54
-	1	83/23,155,210,168,425.3,435.ccls. and brick and cut\$4 and recycl\$4	USPAT; US-PGPUB	2003/11/18 18:56
-	3486	83/23,155,210,168,425.3,435,620,651.1,620.	USPAT; US-PGPUB	2003/11/18 18:56
-	1	83/23,155,210,168,425.3,435.ccls. and brick and cut\$4 and recycl\$4	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2003/11/18 18:56

-	3780	83/23,155,210,168,425.3,435,620,651.1,620.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2003/11/18 18:56
-	23	83/23,155,210,168,425.3,435,620,651.1,620. and brick and cut\$4	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2003/11/18 18:57
-	0	5216963.URPN.	USPAT	2003/11/18 18:58
-	8	("0446338"   "4173910"   "4211130"   "4326439"   "4450739"   "4646598"   "4682524"   "4829863").PN.	USPAT	2003/11/18 18:58
-	10	"547746"	USPAT; US-PGPUB	2003/11/21 10:32
-	4	4557246.URPN.	USPAT	2003/11/21 10:11
-	0	6540501.URPN.	USPAT	2003/11/21 10:13
-	21	("1229582"   "1877269"   "2958163"   "3067731"   "RE27109"   "3580235"   "3660214"   "3664068"   "3918210"   "4048977"   "4393856"   "4557246"   "4691684"   "4865887"   "5085008"   "5133915"   "5316465"   "5492550"   "5496206"   "5979002"   "6109906").PN.	USPAT	2003/11/21 10:13
-	4	5085008.URPN.	USPAT	2003/11/21 10:24
-	9	("2178491"   "2516840"   "2554079"   "2804723"   "2925691"   "3220146"   "3447268"   "3851854"   "4708309").PN.	USPAT	2003/11/21 10:24
-	3	4393856.URPN.	USPAT	2003/11/21 10:25
-	6	("2958163"   "3575155"   "3895722"   "3918210"   "4164279"   "4165006").PN.	USPAT	2003/11/21 10:27
-	3	("0547746"   "1031107"   "1563081").PN.	USPAT	2003/11/21 10:31
-	1	547746.URPN.	USPAT	2003/11/21 10:31
-	79	125/26.ccls.	USPAT; US-PGPUB	2003/11/21 10:47
-	0	125/\$.ccls. and (brake adj clean\$4) and clamp	USPAT; US-PGPUB	2003/11/21 10:48
-	0	125/\$.ccls. and (brick adj clean\$4) and clamp	USPAT; US-PGPUB	2003/11/21 10:48
-	136042	125/\$.ccls. and brick same clean\$4 or remov\$4 and clamp	USPAT; US-PGPUB	2003/11/21 10:49
-	0	125/\$.ccls. and brick same (clean\$4 or remov\$4) and clamp	USPAT; US-PGPUB	2003/11/21 10:49
-	6	125/\$.ccls. and brick and (clean\$4 or remov\$4) and clamp	USPAT; US-PGPUB	2003/11/21 11:28
-	0	125/3.ccls. and brick and (clean\$4 or remov\$4) and clamp	USPAT; US-PGPUB	2003/11/21 11:34
-	0	125/3.ccls. and brick and clamp	USPAT; US-PGPUB	2003/11/21 11:29
-	3	125/3.ccls. and brick	USPAT; US-PGPUB	2003/11/21 11:35
-	3	4393856.URPN.	USPAT	2003/11/21 11:29
-	16	("1915751"   "2732590"   "2884921"   "2901868"   "2958163"   "3233369"   "3384065"   "3410259"   "3945151"   "4256078"   "4393856"   "4557246"   "5018504"   "5129190"   "5423717"   "5496206").PN.	USPAT	2003/11/21 11:29
-	6	("2958163"   "3575155"   "3895722"   "3918210"   "4164279"   "4165006").PN.	USPAT	2003/11/21 11:30
-	2	126/5.ccls. and brick	USPAT; US-PGPUB	2003/11/21 11:32

-	729	brick and (clean\$4 or remov\$4) and clamp	USPAT; US-PGPUB	2003/11/21 11:34
-	3	125/5.ccls. and brick	USPAT; US-PGPUB	2003/11/21 11:35
-	3	125/3.ccls. and brick	USPAT; US-PGPUB	2003/11/25 16:26
-	3	4393856.URPN.	USPAT	2003/11/25 13:41
-	0	125/3.ccls. and conveyor and clamping	USPAT; US-PGPUB	2003/11/25 16:27
-	29	conveyor same clamping same cutters	USPAT; US-PGPUB	2003/11/25 16:48
-	5	5496206.URPN.	USPAT	2003/11/25 16:47
-	1481	144/245.3,245.2,245.1,402,3.1,357.ccls. conveyor same clamping same cutters	USPAT; US-PGPUB	2003/11/25 16:49
-	2	144/245.3,245.2,245.1,402,3.1,357.ccls. and conveyor same clamping same cutters	USPAT; US-PGPUB	2003/11/25 16:49
-	0	269/50.ccls. and conveyor and clamping and cutters	USPAT; US-PGPUB	2003/11/25 16:50
-	12	269/50.ccls. and conveyor	USPAT; US-PGPUB	2003/11/25 16:50
-	20	144/245.3,245.2,245.1,402,3.1,357.ccls. and conveyor and clamping and cutters	USPAT; US-PGPUB	2003/11/25 16:51